


Fig. 1

Fig. 2



240




Fig. 3

Start





Fig. 4

Fig. 5

420

Angle	Cosine	Sine
-2/128	0.995185	-0.146730
-1/128	0.998795	-0.049068
0	1.0	0.0
1/128	0.998795	0.049068
2/128	0.995185	0.098017
3/128	0.989177	0.146730
...
...
...
...
14/128	0.707107	0.634393
15/128	0.773011	0.671559
1/8	0.707107	0.707107
17/128	0.671559	0.740950
18/128	0.634393	0.773011



680

Fig. 6

Angle	Cosine	X_n	Y_n
-2/128	0.995185		
-1/128	0.998795		
0	1.0		
1/128	0.998795		
2/128	0.995185		
3/128	0.989177		
...	
...	
...	
14/128	0.773011		
15/128	0.740951		
1/8	0.707107		
17/128	0.671559		
18/128	0.634393		


692

Fig. 7

Angle	Sine	x_n	y_n
		-2/128	-0.146730
		-1/128	-0.049068
		0	0.0
		1/128	0.049068
		2/128	0.098017
		3/128	0.146730
	
	
		14/128	0.634393
		15/128	0.671559
		1/8	0.707107
		17/128	0.740951
		18/128	0.773011

691-

Fig. 8






Fig. 9